



Inspection Report


Inspection Date: 2017/09/14

Excavators


General Information			
Maker	YANMAR		
Model Number	B3-5		
Year	2003		
Hour (h)	4624	Meter	Working
Serial Number	50576B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		420		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
- The rubber shoes have deteriorated over time
- The rubber shoes are partly worn and cracked


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2017090364