

## **Inspection Report**

Inspection Date: 2017/08/09

### Excavators

General Information		
Maker	YANMAR	
Model Number	Vio40-3	
Year	2004	
Hour (h)	2223 Meter	Working
Serial Number	30643B	

#### **Upper Structure**

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	No
	Right	N/A	N/A	NO
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		620		

### Undercarriage

Undercarnage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	350	350
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК


Engine	
Model	3TNV88-XBV
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	ОК
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

# Options - CNP - Speed changer - Multilever - Blade - EPA

### Note for External Appearance

- Repainted
- The bottom frame has some rust





The rubber shoes have deteriorated over time and are worn



### Note for Operating Component

- Torn seat
- The door of the multi lever is lost
- The canopy is deformed



### Note for Engine

- Engine blow by
- The muffler is partly deformed



Admin No.

2017080149

\*This report is only for your reference. We are not responsible for the actual condition of checked item