



Inspection Report

Inspection Date: 2017/08/16

Excavators

General Information			
Maker	KOMATSU		
Model Number	PC75UU-3		
Year	1997		
Hour (h)	5234	Meter	Working
Serial Number	15254		

Options	
- CAB	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)		650		

Note for External Appearance
The side covers have cracks and dents


Undercarriage		
Shoe Type	Load liner	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- 4 sides reinforced
- No boom cylinder covers


Note for Undercarriage
Some rubber pads are lost/cracked/worn


Engine	
Model	4D102E-1-A
Serial Number	26221545
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component
The window of the canopy has cracks


Note for Engine


Admin No. 2017080412