



Inspection Report


Inspection Date: 2017/09/12

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-30-3S		
Year	2006		
Hour (h)	2206	Meter	Working
Serial Number	61645		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		430		


Note for External Appearance
- Not original color - The arm has been reinforced


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No confirmation of movement	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage


Engine	
Model	D1503
Serial Number	06Q0544
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017090032