



# Inspection Report


Inspection Date: 2017/08/08

## Excavators


| General Information |         |       |         |
|---------------------|---------|-------|---------|
| Maker               | KUBOTA  |       |         |
| Model Number        | RX-403S |       |         |
| Year                | 2005    |       |         |
| Hour (h)            | 3490    | Meter | Working |
| Serial Number       | 60138   |       |         |


| Options      |                 |
|--------------|-----------------|
| - CNP        | - Speed changer |
| - Multilever |                 |
| - Blade      |                 |

| Upper Structure  |       |          |              |       |
|------------------|-------|----------|--------------|-------|
|                  |       | Cylinder |              | Play  |
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | Small |
|                  | Right | N/A      | N/A          |       |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Big   |
| Bucket Size (mm) |       | 550      |              |       |


| Note for External Appearance  |
|---|
| Repainted   |
|  |

| Undercarriage   |           |       |
|-----------------|-----------|-------|
| Shoe Type       | Rubber    |       |
| Swing Circle    | Unchecked |       |
|                 | Left      | Right |
| Shoe Width (mm) | 300       | 300   |
| Idler           | OK        | OK    |
| Sprocket        | OK        | OK    |
| Pin Bush        | OK        | OK    |
| Upper Roller    | OK        | OK    |
| Track Roller    | OK        | OK    |
| Shoe Link       | OK        | OK    |

| Note for Upper Structure  |
|---|
|  |

| Note for Undercarriage  |
|---|
| Oil leak from the travel motors   |
|  |

| Engine           |               |
|------------------|---------------|
| Model            | D1503-KA      |
| Serial Number    | 500180        |
| Engine Oil Leak  | No oil leak   |
| Engine Oil Gauge | OK            |
| Radiator         | OK            |
| Exhaust Color    | Normal        |
| Blow-by          | No            |
| Engine Sound     | OK            |
| Hydraulic Pump   | No oil leak   |
| Water Pump       | No water leak |
| Oil Cooler       | No oil leak   |
| Motor            | Unchecked     |
| Multi Lever      | No oil leak   |

| Note for Operating Component  |
|---|
|  |

| Note for Engine   |
|---|
|  |

Admin No. 2017080142