



# Inspection Report

Inspection Date: 2017/08/08

## Asphalt Finisher

### General Information

<b>Maker</b>	SUMITOMO
<b>Model Number</b>	HA25W-2
<b>Year</b>	1997
<b>Hour</b>	3724
<b>Serial Number</b>	5074

### Engine

<b>Model</b>	V2203-KB
<b>Engine Serial Number</b>	-
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	Not enough cooling water
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for External Appearance

### Note for Control Panel

### Note for Engine

### Other

- The brake is not in a good condition
- Oil oozing from the hopper pull point cylinders

Admin. No. 2017080220

\*This report is only for your reference. We are not responsible for the actual condition of checked item.