



Inspection Report


Inspection Date: 2017/08/08

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO20-3		
Year	2005		
Hour (h)	-	Meter	Replaced
Serial Number	32000B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		420		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The speed changer is not in a good condition


Engine	
Model	3TNV76-P
Serial Number	13547
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The hour meter has been replaced (207h+2500h)


Note for Engine


Admin No. 2017080110