



Inspection Report

Inspection Date: 2017/03/10

Wheel Loader

General Information

Maker	MITSUBISHI
Model Number	WS410A
Year	-
Hour (h)	2292
Serial Number	7W507047

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Engine

Model	-
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	No
--	----

Note for External Appearance

Repainted



Note for Upper Structure

Bucket size: 1,670mm



Note for Operating Component

- The flat tires will be repaired before shipment according to the seller
- Tire size: 15.5/60-18



Note for Undercarriage

- CAB
- Heater



Note for Engine

The engine model and serial number are not clear because of the repaint



Admin. No.

2017030021

*This report is only for your reference. We are not responsible for the actual condition of checked item.