



# Inspection Report

Inspection Date: 2016/05/02

## Welder

### General Information

<b>Maker</b>	shindaiwa
<b>Model Number</b>	dgw310mc
<b>Year</b>	
<b>Hour (h)</b>	2723
<b>Serial Number</b>	20972-00010**

### Note for External Appearance

--

### Engine

<b>Model</b>	D722-ES19
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak

### Note for Control Panel

--

### Note for Engine

--