



# Inspection Report


Inspection Date: 2017/10/10

## Excavators


General Information			
Maker	YANMAR		
Model Number	B6-6		
Year	2006		
Hour (h)	4692	Meter	Working
Serial Number	60886B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		560		


Note for External Appearance


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The inside of the arm has some dents


Note for Undercarriage
The rubber shoes have deteriorated over time and are worn


Engine	
Model	4TNV88-P
Serial Number	40112
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The arm crane monitor is not working


Note for Engine


Admin No. 2017100834