



Inspection Report

Inspection Date: 2017/08/14

Excavators

General Information			
Maker	KUBOTA		
Model Number	U-15-3S		
Year	2006		
Hour (h)	2119	Meter	Working
Serial Number	43421		

Options	
- CNP	
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		400		

Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Oil leak from the swing cylinder


Note for Undercarriage
Width adjustable


Engine	
Model	D782-K2A
Serial Number	-
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
Torn seat


Note for Engine
Abnormal sound from the muffler


Admin No. 2017080087