



Inspection Report


Inspection Date: 2017/10/11

Excavators


General Information			
Maker	YANMAR		
Model Number	ViO30-2		
Year	2003		
Hour (h)	3335	Meter	Working
Serial Number	25989B		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		470		


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The bucket has a hole


Note for Undercarriage
Traveling motion is unchecked


Engine	
Model	3TNE82A-E8VC
Serial Number	82478
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly worn


Note for Engine
The battery is flat


Admin No. 2017100765