



Inspection Report

Inspection Date: 2016/05/12

Mini Excavator

General Information

Maker	Kubota
Model Number	RX303S
Year	
Hour (h)	3708
Serial Number	61034

Note for External Appearance

Oil oozing from the bottom of the body



Upper Structure

Boom Cylinder	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	430
Swing	No backlash and play

Note for Upper Structure

Slight backlash



Operating Component

Speed Pedal	#N/A
--------------------	------

Note for Operating Component



Undercarriage

Swivel Joint	#N/A	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Carrier Roller	NG	OK
Shoe Link	OK	OK

Note for Undercarriage

- Oil oozing from carrier rollers
- Oil leak from the inside of the drive motor



Engine

Model	D1503
Serial Number	600437
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak

Note for Engine

