

## **Inspection Report**

Inspection Date: 2017/09/13

### Excavators

| General Information |                   |         |
|---------------------|-------------------|---------|
| Maker               | CAT               |         |
| Model Number        | 308C              |         |
| Year                | 2004              |         |
| Hour (h)            | 1434 Meter        | Working |
| Serial Number       | CAT0308CACPE01848 |         |

#### **Upper Structure**

|                  |       | Cylinder |              | Play  |
|------------------|-------|----------|--------------|-------|
|                  |       | Oil Leak | Scratch/Rust |       |
| Boom             | Left  | No       | No           | Small |
|                  | Right | N/A      | N/A          | Sman  |
| Arm              |       | No       | No           | Small |
| Bucket           |       | No       | No           | Big   |
| Bucket Size (mm) |       | 710      |              |       |

#### Undercarriage

| enaerearnage    |                              |       |
|-----------------|------------------------------|-------|
| Shoe Type       | Steel shoes with rubber pads |       |
| Swing Circle    | No oil leak                  |       |
|                 | Left                         | Right |
| Shoe Width (mm) | 450                          | 450   |
| Idler           | ОК                           | ОК    |
| Sprocket        | ОК                           | ОК    |
| Pin Bush        | ОК                           | ОК    |
| Upper Roller    | ОК                           | ОК    |
| Track Roller    | ОК                           | ОК    |
| Shoe Link       | ОК                           | ОК    |
|                 |                              |       |


| Engine           |                             |
|------------------|-----------------------------|
| Model            | 4M40-E1                     |
| Serial Number    |                             |
| Engine Oil Leak  | No oil leak                 |
| Engine Oil Gauge | ОК                          |
| Radiator         | ОК                          |
| Exhaust Color    | Normal                      |
| Blow-by          | No                          |
| Engine Sound     | NG                          |
| Hydraulic Pump   | No oil leak                 |
| Water Pump       | No water leak               |
| Oil Cooler       | No oil leak                 |
| Motor            | No confirmation of movement |
| Multi Lever      | No oil leak                 |
|                  |                             |

# Options - CAB - Multilever - Blade - Arm Crane - EPA

#### Note for External Appearance



| Note for Upper Structure |  |
|--------------------------|--|
|                          |  |
|                          |  |
|                          |  |
|                          |  |





#### Note for Engine

The water pump is broken



Admin No.

2017090482

\*This report is only for your reference. We are not responsible for the actual condition of checked item.