



# Inspection Report


Inspection Date: 2017/10/11

## Excavators


General Information			
Maker	KOMATSU		
Model Number	PC58UU-3		
Year	2003		
Hour (h)	3858	Meter	Working
Serial Number	20921		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Unchecked
Bucket		No	No	Big
Bucket Size (mm)				


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
No bucket


Note for Undercarriage


Engine	
Model	4D88E-3GB
Serial Number	22820
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine


Admin No. 2017100795