



# Inspection Report


Inspection Date: 2017/08/17

## Excavators


General Information			
Maker	SUMITOMO		
Model Number	SH225X-3		
Year	2006		
Hour (h)	7795	Meter	Working
Serial Number	225X3-5149		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pipings
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		1030		


Note for External Appearance
- Repainted - The body has some dents


Undercarriage			
Shoe Type	Steel		
Swing Circle	Oil oozing		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure


Note for Undercarriage
The shoe plates have some cracks


Engine	
Model	BB-6BG1TRB-07
Serial Number	-
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The air outlet of the air conditioner has cracks


Note for Engine


Admin No. 2017080406