



# Inspection Report

Inspection Date: 2017/09/15


## Excavators

General Information			
Maker	KOMATSU		
Model Number	PC28UU-3		
Year	2005		
Hour (h)	4446	Meter	Working
Serial Number	32013		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		420		

Note for External Appearance
- The body is not clean - Repainted
The following items are NOT for sale: - The connecting parts of the attachment - The light near the cabin




Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The tip of the arm has some dents




Note for Undercarriage
The rubber shoes have deteriorated over time and are partly cracked




Engine	
Model	3D82AE-3HB
Serial Number	18173
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	No confirmation of movement
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No confirmation of movement
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine
The side covers don't open smoothly



Admin No. 2017090369