



# Inspection Report

Inspection Date: 2016/09/13

## Mini Excavator

### General Information

Maker	KUBOTA
Model Number	U-50-3
Year	2004
Hour (h)	574(実メーターではない)
Serial Number	103**

### Note for External Appearance

Repainted



### Upper Structure

Boom Cylinder	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	Oil leak
Bucket Width (mm)	550
Swing	Backlash and play

### Note for Upper Structure

The bucket a play



### Operating Component

Speed Pedal	Yes
-------------	-----

### Note for Operating Component



### Undercarriage

Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage



### Engine

Model	V2203KA
Serial Number	4E1649
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak

### Note for Engine



admin No

2016090012

\*This report is only for your reference. We are not responsible for the actual condition of checked item.