



Inspection Report


Inspection Date: 2017/08/08

Excavators


General Information			
Maker	KOMATSU		
Model Number	PC38UU-3		
Year	2004		
Hour (h)	4121	Meter	Working
Serial Number	KMTPC018J05009083		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		520		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
Complete washing not applicable (bucket)


Note for Undercarriage


Engine	
Model	3D84E-3MB1
Serial Number	44742
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2017080138