



Inspection Report

Inspection Date: 6/28/2016

Excavator

General Information

| | |
|----------------------|--------------|
| Maker | KOBELCO |
| Model Number | SK60SR-1E |
| Year | 2004 |
| Hour (h) | 4615 |
| Serial Number | Y [REDACTED] |

Note for External Appearance



Upper Structure

| | |
|------------------------------|----------------------|
| Boom Cylinder (Left) | No oil leak |
| Boom Cylinder (Right) | No oil leak |
| Arm Cylinder | No oil leak |
| Bucket Cylinder | No oil leak |
| Bucket Width (mm) | 670 |
| Swing | No backlash and play |

Note for Upper Structure




Undercarriage

| | | |
|------------------------|-------------|--------------|
| Swivel Joint | Oil leak | |
| | Left | Right |
| Shoe Width (mm) | 450 | 450 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

Note for Undercarriage



Note for Operating Component



Engine

| | |
|-------------------------|--------------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Engine not working |
| Blow-by | Engine not working |
| Engine Sound | Engine not working |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Engine

- The engine cover will not open
- Flat battery

