



Inspection Report

Inspection Date: 2017/03/10

Wheel Loader

General Information

Maker	CAT
Model Number	910F
Year	-
Hour (h)	5947
Serial Number	1YK03397

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Engine

Model	3114
Serial Number	2ZF09325
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	Not enough cooling water

Documents

Automobile Inspection Certificate	Yes
--	-----

Note for External Appearance



Note for Upper Structure

Bucket size: 2,370mm



Note for Operating Component

Tire size: 16.5-24



Note for Undercarriage

- CAB
- Heater



Note for Engine



Admin. No.

2017030023

*This report is only for your reference. We are not responsible for the actual condition of checked item.