



# Inspection Report


Inspection Date: 8/3/2016

## Excavator

### General Information

|                      |                     |
|----------------------|---------------------|
| <b>Maker</b>         | KATO                |
| <b>Model Number</b>  | HD1430-LC           |
| <b>Year</b>          |                     |
| <b>Hour (h)</b>      | 5159                |
| <b>Serial Number</b> | KW [REDACTED] 05763 |

### Note for External Appearance



### Upper Structure

|                              |                   |
|------------------------------|-------------------|
| <b>Boom Cylinder (Left)</b>  | No oil leak       |
| <b>Boom Cylinder (Right)</b> | No oil leak       |
| <b>Arm Cylinder</b>          | No oil leak       |
| <b>Bucket Cylinder</b>       | Oil leak          |
| <b>Bucket Width (mm)</b>     | 0                 |
| <b>Swing</b>                 | Backlash and play |

### Note for Upper Structure




### Undercarriage

|                        |             |              |
|------------------------|-------------|--------------|
| <b>Swivel Joint</b>    | No oil leak |              |
|                        | <b>Left</b> | <b>Right</b> |
| <b>Shoe Width (mm)</b> | 600         | 600          |
| <b>Idler</b>           | OK          | OK           |
| <b>Sprocket</b>        | OK          | OK           |
| <b>Pin Bush</b>        | OK          | OK           |
| <b>Upper Roller</b>    | OK          | OK           |
| <b>Track Roller</b>    | OK          | OK           |
| <b>Shoe Link</b>       | OK          | OK           |

### Note for Undercarriage



### Note for Operating Component



### Engine

|                         |               |
|-------------------------|---------------|
| <b>Model</b>            |               |
| <b>Serial Number</b>    |               |
| <b>Engine Oil Leak</b>  | No oil leak   |
| <b>Engine Oil Gauge</b> | OK            |
| <b>Radiator</b>         | OK            |
| <b>Exhaust Color</b>    | Normal        |
| <b>Blow-by</b>          | No            |
| <b>Engine Sound</b>     | OK            |
| <b>Hydraulic Pump</b>   | No oil leak   |
| <b>Water Pump</b>       | No water leak |
| <b>Oil Cooler</b>       | No oil leak   |
| <b>Motor</b>            | No oil leak   |
| <b>Multi Lever</b>      | No oil leak   |

### Note for Engine

