Inspection Report

Inspection Date: 2026/11/12

Wheel Loader

General Information	
Maker	BOBCAT
Model Number	315
Year	
Hour (h)	1317
Serial Number	4988A3811JAM

Upper Structure	
Lift Arm Cylinder (Left)	Oil leak
Lift Arm Cylinder (Right)	Oil leak
Bucket Cylinder (Left)	Oil leak
Bucket Cylinder (Right)	Oil leak

Undercarriage	
Front Accel	No oil leak
Rear Accel	No oil leak

Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Unchecked
Blow-by	Unchecked
Engine Sound	Unchecked
Water Pump	No water leak
Radiator	Not enough cooling water

Documents	
Automobile Inspection Certificate	No

Note for External Appearance

- The body has scratches, rust, and corrosion



Note for Upper Structure

- The cylinder has rust



Note for Operating Component



Note for Undercarriage

- The rear right tire is flat



Note for Engine

- The engine does not operate
- The radiator cap is damaged



Admin. No. 3000091893

*This report is only for your reference. We are not responsible for the actual condition of checked item.