



Inspection Report


Inspection Date: 2022/11/26

Excavators


General Information			
Maker	KUBOTA		
Model Number	RX-505		
Year	2009		
Hour (h)	4559	Meter	Working
Serial Number	70625		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		630		


Note for External Appearance


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The blade is partly deformed


Engine	
Model	V2203
Serial Number	9U3165
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Undercarriage


Note for Operating Component


Note for Engine


Admin No. 3000044445