



Inspection Report

Inspection Date: 2021/05/07

Excavators

General Information

Maker	CAT		
Model Number	320D		
Year	2009		
Hour (h)	9414	Meter	Working
Serial Number	CAT0320DHBWZ03120		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Arm Crane	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		Oil oozing	No	No
Bucket		No	No	Big
Bucket Size (mm)	1140			

Note for External Appearance

- The body is rusty, damaged, and repainted
- The covers have some dents



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	800	800
Idler	OK	OK
Sprocket	NG	NG
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	NG	NG
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Oil oozing from the lower rollers



Engine

Model	C6.4
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- Crane mode error
- The right control lever cover has been detached
- A cylinder error message appears on the monitor



Note for Engine

- The air conditioner belt has been detached



Admin No. 3000031102