



# Inspection Report

Inspection Date: 2022/08/31


## Excavators

General Information			
Maker	HITACHI		
Model Number	ZX30U-5A		
Year	2014		
Hour (h)	1465	Meter	Working
Serial Number	HCMADBA0C00033342		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Piping


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Small
Bucket Size (mm)	450			

Note for External Appearance
- The left side of the body is rusty



Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- Some dents inside the tip of the arm




Note for Undercarriage
------------------------



Engine	
Model	3TNV88
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
------------------------------



Note for Engine
-----------------



Admin No. 3000042443