

ZX125W Wheel Shovel

BASIC INFORMATION

| | | | | | |
|-----------------------|--------------------------------------|----------------------|--|------------------------|--------------|
| Inspection Date | | Model | ZX125W | Serial No. | 6277 |
| Date of Manufacture | | Hourmeter | 22959 HR | Condition of Hourmeter | HR is normal |
| Hourmeter (Estimated) | | Mileage | | Engine No. | |
| Job Status | General Contractor/Civil Engineering | Accident History | | Cabin Type | Standard |
| Front Attachment | Standard | License Number Plate | None | Bucket/Attachment | Standard BK |
| Drive System | All Wheel Drive | Type of Tire | Double | Size of Tire | 9.00-20-12PR |
| Stamp | | Others | Air Conditioner, ML Crane, Piping, Blade | | |

OPERATION

| | | | | | |
|---------------------|-------------------------------|-------------------|---------------------------------|------------------|--------|
| Engine | Normal | Exhaust Gas Color | Normal | Swing | Normal |
| Wear: Swing Bearing | Moderate/Within Service Limit | Traveling | Normal ラムシッダー、ロックが解除していない感じ。 | Front Attachment | Normal |
| Outrigger | | Steering | Normal | Break | Normal |
| Side Break | Normal | Pump Device | Normal | | |

UNDERCARRIAGE/CHASSIS/TIRES

| | | | | | |
|-----------------------------------|----------|----------------------------------|----------|----------------------------------|----------|
| Scrathes: Tire(Front-Right Wheel) | Moderate | Wear: Tire(Front-Right wheel) | Moderate | Scrathes: Tire(Front-Left Wheel) | Moderate |
| Wear: Tire(Front-Left Wheel) | Moderate | Scrathes: Tire(Rear-Right Wheel) | Moderate | Wear: Tire(Rear-Right Wheel) | Moderate |
| Scrathes: Tire(Rear-Right Wheel) | Moderate | Wear: Tire(Rear-Left Wheel) | Moderate | Oil Leak: Axle | No |
| Oil Leak: Differential Gear Case | No | Oil Leak: Stearing Cylinder | No | | |

FRONT & PINS

| | | | | | |
|--------------------------|--|-------------------|-------------------------------|--------------------------|--|
| Boom | Normal | Arm | Reinforcement | Wear: Boom Foot Pin | Moderate/Within Service Limit |
| Wear: Boom/Arm Joint Pin | Moderate/Within Service Limit | Wear: Arm Tip Pin | Moderate/Within Service Limit | Wear/Deformation: Bucket | Wear: Moderate/Within Service Limit, Deformation: Moderate |
| Wear/Deformation: Blade | Wear: Moderate/Within Service Limit, Deformation: Moderate | | | | |

OIL/WATER/AIR LEAK

| | | | | | |
|------------------------------|----|--------------------------------|-----------------|-------------------------------|-------------|
| Oil Leak: Front Pipes | No | Oil Leak: Boom Cylinder(Right) | Moderate Oozing | Oil Leak: Boom Cylinder(Left) | No |
| Oil Leak: Arm Cylinder | No | Oil Leak: Bucket Cylinder | No | Oil Leak: Offset Cylinder | |
| Oil Leak: Blade Cylinder | No | Oil Leak: Outrigger Cylinder | | Oil Leak: Engine | Slight Film |
| Oil Leak: Oil Cooler | No | Leak: Radiator | No | Leak: Cooling Pipes | No |
| Oil Leak: Fuel System | No | Compressor | Normal | Oil Leak: Control Valve | No |
| Oil Leak: Low Pressure Pipes | No | Oil Leak: High Pressure Pipes | Slight Film | Oil Leak: Pilot Pipes | No |
| Oil Leak: Pilot Valve | No | Oil Leak: Center Joint | No | Oil Leak: Swing Device | No |
| Oil Leak: Pump Device | No | | | | |

APPEARANCE

| | | | | | |
|----------------|-----------------|-------------|--------------------------------|--------------|-----------------|
| Engine Cover | Rusted/Corroded | Side Covers | Rusted/Corroded | Under Covers | Rusted/Corroded |
| Counter Weight | Rusted/Corroded | Main frame | Rusted/Corroded | D Frame | Rusted/Corroded |
| Chassis | Rusted/Corroded | Cabin | Deformed/Dent, Rusted/Corroded | Door | Good Condition |

INTERIOR

| | | | | | |
|-----------------|----------------|----------------------|----------------|---------|--------|
| Cabin Interior | Good Condition | Seat | Good Condition | Console | Broken |
| Air conditioner | Good Condition | Freon gas inspection | Good Condition | | |

OVERALL RATING

| | | | | | |
|-----------------------|-----------|----------------|----------|----------------|------|
| Appearance Evaluation | Repainted | Rust/Corrosion | Moderate | Overall Rating | Fair |
| Special Notes | | | | | |