



Inspection Report

Inspection Date: 2026/07/19

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	U40-6		
Year	2014		
Hour (h)	5087	Meter	Working
Serial Number	13056		

Options

- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pippings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		550		

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The rubber pads on both sides are worn



Engine

Model	V2607-DI-EU7
Serial Number	V2607-8EG3473
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- 4-pillar canopy



Note for Engine



Admin No. 3000087714

*This report is only for your reference. We are not responsible for the actual condition of checked item.