



Inspection Report

Inspection Date: 2019/02/22

Wheel Loader

General Information

Maker	KUBOTA
Model Number	RA-601
Year	1994
Hour (h)	2164
Serial Number	10099

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	No
--	----

Note for External Appearance



Note for Upper Structure



Note for Operating Component

The seat is partly torn



Note for Undercarriage

Unable to travel properly



Note for Engine

Oil oozing from around the hoses under the engine



Admin. No. 2019020506

*This report is only for your reference. We are not responsible for the actual condition of checked item.