



Inspection Report

Inspection Date: 2018/03/17

Excavators

General Information

Maker	KUBOTA		
Model Number	RX-505		
Year	2008		
Hour (h)	4684	Meter	Working
Serial Number	70457		

Options

- CNP
- Multilever
- Blade
- Arm Crane
- Speed changer

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)	550			

Note for External Appearance



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

The bucket side cutters are partly worn



Note for Undercarriage

The rubber shoes have been deteriorated over time, are worn, and partly cracked



Engine

Model	V2203
Serial Number	8N6110
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

A hissing sound from around the control valve while the engine is working



Lot No ARA013-0038 Admin No. 2018030708