



Inspection Report

Inspection Date: 2024/08/13

Wheel Loader

General Information

| | |
|---------------|------------|
| Maker | YANMAR |
| Model Number | V3-5B |
| Year | 2006 |
| Hour (h) | 3578 |
| Serial Number | L3DA-53784 |

Note for External Appearance



Upper Structure

| | |
|---------------------------|-------------|
| Lift Arm Cylinder (Left) | No oil leak |
| Lift Arm Cylinder (Right) | No oil leak |
| Bucket Cylinder (Left) | No oil leak |
| Bucket Cylinder (Right) | No oil leak |

Note for Upper Structure



Undercarriage

| | |
|-------------|------------|
| Front Accel | Oil oozing |
| Rear Accel | Oil oozing |

Note for Operating Component

- With CAB (cabin) heater



Engine

| | |
|------------------|---------------|
| Model | 3TNV84-XKAH |
| Serial Number | 30723 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Water Pump | No water leak |
| Radiator | OK |

Note for Undercarriage

- Tire size: 12.5/70-16 6P.R.
- With tire chains



Documents

| | |
|-----------------------------------|----|
| Automobile Inspection Certificate | No |
|-----------------------------------|----|

Note for Engine

- EPA



Admin. No. 3000062469

*This report is only for your reference. We are not responsible for the actual condition of checked item.