



Inspection Report

Inspection Date: 2022/10/11

Excavators

General Information

Maker	CAT		
Model Number	311CU		
Year	2006		
Hour (h)	2919	Meter	Replaced
Serial Number	CAT0311CACLK03839		

Options


- CAB	- Speed changer
- Multilever	- Air conditioner

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	Oil oozing	No	
Arm		No	No	Small
Bucket		Oil oozing	No	Big
Bucket Size (mm)	800			

Note for External Appearance

- The body is rusty and damaged




Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	Oil oozing		
		Left	Right
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

- The bucket is torn and rusty
- The bucket pin lock is missing
- The rotation is not smooth and has plays



Note for Undercarriage

- The frame is rusty and decayed
- The pads are worn and cracked




Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak


Note for Operating Component

- The seat is partly torn
- The inner cover of the cabin is missing



Note for Engine

- Oil leaks from the tappet cover
- Oil oozing from the injection pump line
- Oil oozing from the engine
- Engine blow by



Admin No. 3000042001