



# Inspection Report

Inspection Date: 2024/08/23

## Excavators

### General Information

Maker	KOMATSU		
Model Number	PC138US-8		
Year	2013		
Hour (h)	5726	Meter	Working
Serial Number	KMTPC189C01030142		

### Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	No	No	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		850		

### Note for External Appearance



### Note for Upper Structure

- The upper structure has play and backlash



### Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Undercarriage



### Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000062752

\*This report is only for your reference. We are not responsible for the actual condition of checked item.