

Inspection Report

Inspection Date: 2023/09/07

Excavators

General Information			
Maker	KOMATSU		
Model Number	PC30MR-5		
Year	2016		
Hour (h)	2782 Meter	Working	
Serial Number	KMTPC262EGE050588		

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	Scratch	No
	Right	N/A	N/A	NO
	Arm	No	No	No
	Bucket	No	No	Small
Bucket Siz	ze (mm)	420		

Undercarriage

onaoroannago		
Shoe Type	Rubber	
Swing Circle	Unchecked	
	Left	Right
Shoe Width (mm)	300	300
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

EngineModel3D88E-7ESDASerial Number00896Engine Oil LeakNo oil leakEngine Oil GaugeOKRadiatorOKRadiatorNormalBlow-byNoBlow-byNo oil leakHydraulic PumpNo oil leakWater PumpOil oozingOil CoolerOil oozingMulti LeverNo oil leak

Options - CAB - Speed changer - Multilever - Air conditioner - Blade - Air conditioner

- EPA

Note for External Appearance



Note for Upper Structure	

Note for Undercarriage	

Note for Operating Component	
Note for Engine	



Admin No.

*This report is only for your reference. We are not responsible for the actual condition of checked item