



Inspection Report

Inspection Date: 2026/06/05

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	RX-153S		
Year	2007		
Hour (h)	2203	Meter	Working
Serial Number	40319		

Options


- CNP	- Speed changer
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		350		

Note for External Appearance

- Repainted
- Rotation is not smooth (has play and backlash)




Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	230	230
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Oil leaks from the blade cylinder



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Undercarriage



Note for Operating Component



Note for Engine



Admin No. 3000086141