



# Inspection Report

Inspection Date: 2018/04/13


## Excavators

General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK30SR-5		
<b>Year</b>	2007		
<b>Hour (h)</b>	3525	<b>Meter</b>	Working
<b>Serial Number</b>	PW14-45137		

Options	
- CNP	
- Multilever	
- Blade	- Pippings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		450		

Note for External Appearance
- The boom light cover is deformed
- The body is partly repainted




Undercarriage			
<b>Shoe Type</b>	Rubber		
<b>Swing Circle</b>	No oil leak		
	<b>Left</b>	<b>Right</b>	
<b>Shoe Width (mm)</b>	300	300	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

Note for Upper Structure




Note for Undercarriage
Unable to back up straight (tends to go left)



Engine	
<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018040330