



Inspection Report

Inspection Date: 2026/06/18

Excavators

General Information

Maker	KUBOTA		
Model Number	U30-6		
Year	2015		
Hour (h)	2592	Meter	Working
Serial Number	10965		

Options

- CNP	- Speed changer
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Unchecked
Bucket Size (mm)		0		

Note for External Appearance

- No bucket



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Slight vibration occurs when operating the accelerator at low speed



Note for Undercarriage



Engine

Model	D1703
Serial Number	1968
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component

- Unable to open the cover on the radiator side



Note for Engine



Admin No. 3000088943

*This report is only for your reference. We are not responsible for the actual condition of checked item.