



Inspection Report

Inspection Date: 2019/05/19

Excavators

General Information

Maker	KATO		
Model Number	HD308USV		
Year	2014		
Hour (h)	857	Meter	Working
Serial Number	KWJ08E01HE0006005		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	Yes	No
Bucket Size (mm)	645			

Note for External Appearance

- The counterweight is repainted
- The bucket and the blade are worn and rusty



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	OK	
Shoe Link	OK	OK	

Note for Upper Structure

Some of the bucket-side cutters are lost



Note for Undercarriage

- One of the left lower rollers is in bad condition
- The upper part of the blade is deformed



Engine

Model	AU-4LE2XYSB-01
Serial Number	4LE2-612529
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2019050598