



Inspection Report

Inspection Date: 2022/08/31

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200-8N1		
Year	2007		
Hour (h)	7137	Meter	Working
Serial Number	KMTPC197L02310767		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Arm Crane | - Pipings |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Oil oozing	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)	1065			

Note for External Appearance

- The left side of the body has some dents



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The arm has been reinforced



Note for Undercarriage

- Oil oozing from 1 right lower roller



Engine

Model	SAA6D107E-1-A
Serial Number	26510153
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000042420