



# Inspection Report

Inspection Date: 2021/10/09

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	SV08-1A		
<b>Year</b>	2014		
<b>Hour (h)</b>	1404	<b>Meter</b>	Working
<b>Serial Number</b>	YMRSV08YCEAJ18513		

### Options

- Speed changer
- Multilever
- Blade
- EPA

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)	335			

### Note for External Appearance

- Repainted
-------------



### Undercarriage

<b>Shoe Type</b>	Rubber		
<b>Swing Circle</b>	No oil leak		
		Left	Right
Shoe Width (mm)	200	200	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


### Note for Upper Structure

--



### Note for Undercarriage

- The width between the shoes is adjustable from 680mm to 840mm
---



### Engine

<b>Model</b>	2TE67L-BV3
<b>Serial Number</b>	14839
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

--



### Note for Engine

--



Admin No. 3000034861