



Inspection Report

Inspection Date: 2019/02/18


Excavators

General Information			
Maker	SUMITOMO		
Model Number	SH125XU-3		
Year	2004		
Hour (h)	8735	Meter	Working
Serial Number	125X3-5140		

Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	Oil oozing	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		810		

Note for External Appearance




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage




Engine	
Model	BB-4BG1TRA-03
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	Not enough cooling water
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn



Note for Engine
The radiator tank is damaged



Admin No. 2019020328