



Inspection Report

Inspection Date: 2018/09/15

Excavators

General Information

Maker	YANMAR		
Model Number	B6-6A		
Year	2008		
Hour (h)	3424	Meter	Working
Serial Number	62011B		

Options

- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)	610			

Note for External Appearance




Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)	400	400	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure

The blade won't go down

Note for Undercarriage



Engine

Model	3NNPE
Serial Number	86899
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn

Note for Engine



Admin No. 2018090184