



Inspection Report

Inspection Date: 2018/02/20

Wheel Loader

General Information

Maker	CAT
Model Number	910E
Year	1991
Hour (h)	6372
Serial Number	1YK00609

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

Engine

Model	
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Exhaust Color	White
Blow-by	Yes
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	Yes
--	-----

Note for External Appearance

- Repainted
- The engine cover is partly rusty



Note for Upper Structure

Oil oozing from the swing cylinder



Note for Operating Component

A/C



Note for Undercarriage

Tire size: 16.9-24



Note for Engine

- White exhaust gas
- Engine blowby



Admin. No. 2018020302

*This report is only for your reference. We are not responsible for the actual condition of checked item.