



# Inspection Report

Inspection Date: 2022/08/17

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	ViO20-3		
<b>Year</b>	2015		
<b>Hour (h)</b>	1684	<b>Meter</b>	Working
<b>Serial Number</b>	3B469		

### Options

- |              |                 |
|--------------|-----------------|
| - CNP        | - Speed changer |
| - Multilever |                 |
| - Blade      |                 |

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	425			

### Note for External Appearance



### Undercarriage

<b>Shoe Type</b>	Rubber	
<b>Swing Circle</b>	No oil leak	
	<b>Left</b>	<b>Right</b>
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

### Note for Upper Structure



### Note for Undercarriage



### Engine

<b>Model</b>	
<b>Serial Number</b>	G2610
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component



### Note for Engine



Admin No. 3000042494