



Inspection Report

Inspection Date: 2019/01/16


Excavators

General Information			
Maker	SUMITOMO		
Model Number	SH75X-3		
Year	2007		
Hour (h)	5673	Meter	Working
Serial Number	075X3-6193		

Options	
- CAB	
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		720		

Note for External Appearance
- The covers are partly deformed - Concrete adheres to the truck frame, blade, and the bucket




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage
Oil oozing from the reduction drive of the right travel motor



Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 2018120376