



Inspection Report

Inspection Date:

Spider Crane

General Information

Maker	MAEDA
Model Number	MC-285CWM
Year	
Hour (h)	301
Serial Number	P00297

Engine

Model	
Serial Number	
Engine Oil Leak	
Engine Oil Gauge	
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	
Water Pump	
Injection Pump	

Note for External Appearance

- The body has rust and scratches
- Oil oozing some slinder

Note for Control Panel

Note for Engine

- Slight white smoke when the engine starts

Other Information

- The operation is slow

Admin. No. 3000081689

*This report is only for your reference. We are not responsible for the actual condition of checked item.