



Inspection Report

Inspection Date: 2022/06/04


Excavators

General Information			
Maker	HOKUETSU		
Model Number	AX20U-4		
Year	2010		
Hour (h)	1902	Meter	Working
Serial Number	1MYB010394		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		Oil oozing	No	Small
Bucket Size (mm)		400		

Note for External Appearance
- Repainted



Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	250	250	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- Oil oozing from around the blade cylinder




Note for Undercarriage




Engine	
Model	S773L
Serial Number	
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
- Oil severely oozing from around the oil filter



Admin No. 3000040340