

# **Inspection Report**

## **Excavator**

General Information	
Maker	SUMITOMO
Model Number	SH75X-3
Year	2007
Hour (h)	4235
Serial Number	0

#### Lippor Structure

Opper Structure	
Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	720
Swing	Backlash and play

#### Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	NG
Shoe Link	OK	OK

Engine	
Model	4TNE98-SH
Serial Number	33937
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

#### Note for External Appearance



Repainted



#### Note for Upper Structure

- The arm and bucket have plays
- Pipings - Arm crane
- The blade has a dent



2 worn lower rollers (right)

### Note for Operating Component

- Torn sheet - Multi lever



Note for Engine	