



Inspection Report

Inspection Date: 2018/09/19


Excavators

General Information			
Maker	HITACHI		
Model Number	ZX70-3		
Year	2014		
Hour (h)	20	Meter	Working
Serial Number	HCM1P100P00084782		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- EPA	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		655		

Note for External Appearance
- Unused
- The date of manufacture: Oct. 2014




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	450	450	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
4 sides of the arm have been reinforced




Note for Undercarriage



Engine	
Model	Au-4LE2XYSA-01
Serial Number	4LE2-624179
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
Rear-view camera



Note for Engine



Admin No. 2018090307