



Inspection Report

Inspection Date: 2018/08/08


Excavators

General Information			
Maker	KOBELCO		
Model Number	SK130UR-1ES		
Year			
Hour (h)	6110	Meter	Working
Serial Number	YX05-02172		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		800		


Note for External Appearance



Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	500	500	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	


Note for Upper Structure

The right side of the tip of the arm has been partly fixed (please check the pictures)



Note for Undercarriage


The rubber pads are partly worn



Engine	
Model	BB-4BG1 TRY
Serial Number	4BG1-934802
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

The surface of the seat is partly torn



Note for Engine



Lot No. ARA017-0021 Admin No. 2018080004